

FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020
 Division : Muzaffargarh District : Muzaffargarh
 Name of the Road : Muzaffargarh - Chakrabarty Road Length (km): 2.90
 Scheme/Programme : MAINTENANCE
 Package No.:
 Status of the Project: Road Id No.: 31507413056
 Work is a case of: Ongoing/Completed/Under Maintenance
 New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S Yes/No
f)	Contraction Joints provided or not (CC Pavement)	S Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating : Satisfactory (S) S
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U)

22/12/2020
 (Signature)

NAME: Dervendha Datta
 DESIGNATION: AE