## FIELD INSPECTION REPORT

		FIELD HASPEC	LIION REPORT	
Date o	of Inspection: 2	4.12.20	District: East champar	. ·
DIVISION: Kaxaul			Longth (long), A. O.C.	
Name	of the Road: 10	KLOUYE A	Lapur road to Baikur	V 11
		MAINTENANCE	MASY	THA NAM
	ge No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance		
	is a case of:	New Connectivity/U	p gradation/ Maintenance	
Sl. No.		Parameters to be elecked		Remarks
1.	Pavement			
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			√S/U
c)	Riding Quality			~5/U
d)				√S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
1)	Contraction Joints provided or not (CC Pavement)  Xes/No			
g)	Compaction of flank/slope & raincuts if any  Yes/No			
2.	Cross Drainage			
ก)	Condition of head walls in Hume pipe culverts including its painting \sqrt{S/SRI/U}			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts X,SRI/U			
c)	Condition of railings/slab/approach for Bridges  S/SRI/U			
3.	Road Furniture			
a\ /	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
) S	Status of ATR's & any others			N.A.

Overall Rating

Satisfactory (S)	(\$1
Satisfactory but requires	Improvement (SRI)
Unsatisfactory (U)	

(Signature)

NAME: Styam Sundar Roy DESIGNATION: A. E. Chlauradaro