

FIELD INSPECTION REPORT

Date of Inspection: 25/12/2020	District: Samastipur
Division: ROSERA	Length (km): 1.930 km
Name of the Road: 1926 To, to Haripur (VR-10)	
Scheme/Programme: MAINTENANCE	✓
Package No.: BR-30R-404	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

Some pots and patches developed need to repairs immediately
 25/12/2020
 J.E.

25/12/2020
 J.E./Rosera-1
 (Signature)

NAME: DINDAYAL CHOUHAN
 DESIGNATION: J.E./R.W.D, ROSER-1