


FIELD INSPECTION REPORT

Date of Inspection:	Division: <u>RWD works Dtr ROSERA</u>	District: <u>SAMASTIPUR.</u>
Name of the Road: <u>TO, to Majraha (VR-45)</u>	Length (km):	
Scheme/Programme: <u>MAINTENANCE</u>	Road Id No.:	
Package No.: <u>BR-30A</u>	Status of the Project: <u>Ongoing/Completed/Under Maintenance</u>	
Work is a case of: <u>New Connectivity/Up gradation/ Maintenance</u>		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	<u>SRI</u>
Unsatisfactory (U)	


 19/12/20
 J.E. Subrajit Narayan
 (Signature)

NAME: Sukhit Narayan
 DESIGNATION: J.E.