

FIELD INSPECTION REPORT

Date of Inspection :	District: SAMASTIPUR.
Division : RWD works DN ROSORA	Length (km):
Name of the Road: LOGA to Buniyadpur (VR-47)	
Scheme/Programme: MAINTENANCE PMGSY	
Package No.: DR-30R-433	Road Id No.:
Status of the Project: Ongoing Completed Under Maintenance ✓	
Work is a case of: New Connectivity Up gradation Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings, slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)
19/12/20
J.E. Sarvagya Nagar

NAME: **Sukhit Narayan**
DESIGNATION: **J.E.**