

FIELD INSPECTION REPORT

Date of Inspection :	District: <u>SAMASTIPUR.</u>
Division : <u>RWD works Dtr ROSRA</u>	Length (km):
Name of the Road: <u>TOZ Bhakar to Phulwari, MCH</u>	
Scheme/Programme: <u>MAINTENANCE</u>	
Package No.:	Road Id No.:
Status of the Project: <u>Ongoing</u>	Completed/Under Maintenance
Work is a case of: <u>New Connectivity</u>	Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note - Due to flood BT surface damaged.


(Signature)

NAME: Raw Shankar Kumar

DESIGNATION: Assistant Engineer, Stylic