## FIELD INSPECTION REPORT

Date of Inspection:	17-12-9070	District: Kathan	
Division: Manitarn		Length (km): 0-1460 kH	
Name of the Road:	L061 - TO2 -	to Guni Tola.	
Scheme/Programme:	MAINTENANCE		
Package No.: BR-16R-307		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	<b>√8/U</b>
b) ·	Condition of Surfacing	√8/U
c)	Riding Quality	<b>√8/U</b>
d)	Road Camber	√8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
<b>2</b> .	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	8/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	√8/SRI/U
c)	Condition of railings/slab/approach for Bridges	√8/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	9
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Romchardsa Rom DESIGNATION: J-E-