## FIELD INSPECTION REPORT

Date of Inspection:	17-12-2020	District:	Kattlan	
Division:	Janitan	Length (km):	1.470 KH	
Name of the Road:	L022 TO Pat	harbar CT	rack 5)	
Scheme/Programme:	MAINTENANCE			
Package No.: BR-16R-364		Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks		
1,	Pavement	The state of the s		
a)	Road Junction condition	<b>√8/U</b>		
b)	Condition of Surfacing	√8/U		
c)	Riding Quality			
d)	Road Camber	√8/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No		
f)	Contraction Joints provided or not (CC Pavement)	Yés/No		
g)	Compaction of flank/slope & raincuts if any	Yés/No		
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	√8/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S∕/SRI/U		
c)	Condition of railings/slab/approach for Bridges	S/SRI/U		
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No		
4.	Compliance History			
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Romohandson Com

DESIGNATION: J-E

Scanned by CamScanner

(Signature)