FIELD INSPECTION REPORT

| Date of Inspection: 19/12/2020 | | | District: Muzafforpud | |
|---|--|--|--|-----------------------------|
| Divisio | n: NWOW | est | Tonath (1m). 3.00 1.010 | Kan |
| Name o | of the Road: L | 087 se Kanuco | a Tak | 9 |
| Scheme | e/Programme: | MAINTENANCE | 0.00001.1900 | 2 |
| Packag | | | Road Id No.: 3150741800 | 3 |
| Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance | | | | |
| Work is | s a case of: | - A TO STORY THE COURT OF THE PARTY OF THE P | | Disales |
| SI. No. | | Parameters to | be checked | Remarks |
| 1. | Pavement | | | determination of the second |
| a) | Road Junction condition | | | S/U |
| b) | Condition of Surfacing | | | S/U |
| c) | Riding Quality | | | S/U |
| d) | Road Camber | | | S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) yes | | | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | | | Yes/No |
| 2. | Cross Draina | ge | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | | | 8/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts N/A | | | S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | | | S/SRI/U |
| 3, | Road Furnitu | re | and the state of t | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | Yes/No |
| 4. | Compliance H | istory | | |
| a) | Status of ATR's | s & any others | | NO ATR |

Overall Rating

| Satisfactory (S) | S |
|---|---|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

(Signature)

NAME: AMJAD TAMALI

DESIGNATION: JUNIOR ENCINEER