

# FIELD INSPECTION REPORT

Date of Inspection :	18/12/20	District:	East Champaran
Division :	Raxaul	Length (km):	1.062
Name of the Road:	Majapati Samiya to Majapati Hardiya		
Scheme/Programme:	MAINTENANCE	PMGSY	
Package No.:	BR-1/R-636	Road Id No.:	31708502060
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	N.A.

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Mithelesh Kumar Singh