

# FIELD INSPECTION REPORT

|                                                                      |                              |
|----------------------------------------------------------------------|------------------------------|
| Date of Inspection :                                                 | District: <b>SAMASTIPUR.</b> |
| Division : <b>RWD works Dtr ROSERA</b>                               | Length (km): <b>0.780 km</b> |
| Name of the Road: <b>LD39 to Kanchi (VR-55)</b>                      |                              |
| Scheme/Programme: <b>MAINTENANCE PMGSY</b>                           |                              |
| Package No.: <b>BR-30R-536</b>                                       | Road Id No.:                 |
| Status of the Project: <b>Ongoing Completed Under Maintenance</b>    |                              |
| Work is a case of: <b>New Connectivity/Up gradation/ Maintenance</b> |                              |

| Sl. No.   | Parameters to be checked                                                                                             | Remarks   |
|-----------|----------------------------------------------------------------------------------------------------------------------|-----------|
| <b>1.</b> | <b>Pavement</b>                                                                                                      |           |
| a)        | Road Junction condition                                                                                              | ✓ S/U     |
| b)        | Condition of Surfacing                                                                                               | ✓ S/U     |
| c)        | Riding Quality                                                                                                       | ✓ S/U     |
| d)        | Road Camber                                                                                                          | ✓ S/U     |
| e)        | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓ Yes/No  |
| f)        | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ Yes/No  |
| g)        | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No  |
| <b>2.</b> | <b>Cross Drainage</b>                                                                                                |           |
| a)        | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓ S/SRI/U |
| b)        | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U   |
| c)        | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U   |
| <b>3.</b> | <b>Road Furniture</b>                                                                                                |           |
| a)        | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No  |
| <b>4.</b> | <b>Compliance History</b>                                                                                            |           |
| a)        | Status of ATR's & any others                                                                                         |           |

Overall Rating :

|                                             |            |
|---------------------------------------------|------------|
| Satisfactory (S)                            |            |
| Satisfactory but requires Improvement (SRI) | <b>SRI</b> |
| Unsatisfactory (U)                          |            |

*Kommm*  
19/12/20  
(Signature) **J.E. Swagati Narayan**

NAME: **Sukhit Narayan**  
DESIGNATION: **J.E**