

FIELD INSPECTION REPORT

Date of Inspection :	District: SAMASTIPUR.	
Division : RWD works Div ROSERA	Length (km):	
Name of the Road: T02 to Nartoli		
Scheme/Programme: MAINTENANCE PMGSY		
Package No: PMGSY BR-302-	Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance	✓	
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Note:- ^{Partially} Road crust (B.T) and flank damaged due to flood.

(Signature)

NAME: Sukhit Narayan
DESIGNATION: J.E

[Signature]
20/12/20
J.E Singh