

FIELD INSPECTION REPORT

Date of Inspection :	District: <u>SAMASTIPUR.</u>
Division : <u>RWD works Div ROSERA</u>	Length (km): <u> </u>
Name of the Road: <u>LO59 to Usharali tola</u>	
Scheme/Programme: <u>MAINTENANCE</u>	<u>MMUSY</u>
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ☒
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	<u>S</u>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
19/12/20
(Signature) J.E. Rosera

NAME: Sukhit Narayan
DESIGNATION: J.E