FIELD INSPECTION REPORT

100	7.2	
Date of Inspection: 2	0.12.2020	District: Samostibin
Division: R.W.D. Resura.		Length (km): 0.640 Km.
Name of the Road: S:	hma to khai	rokot Utlar Tola.
Scheme/Programme:	MAINTENANCE	
Package No.: —		Road Id No.:
Status of the Project:	Ongoing/Completed	/Under Maintenance
Work is a case of:	New Connectivity/U	Jp gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Payement	
a)	Road Junction condition	S/JJ
b)	Condition of Surfacing :	SIV
c)	Riding Quality	S/W
d)	Road Camber	S/L
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/Mo
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SKI/X
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRY/B
c)	Condition of railings/slab/approach for Bridges	S/SKI/V
CORO AND ALITY	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
Street Sale Street Auct	Status of ATR's & any others	No.

O. erall Rating

Satisfactory (S)	2 د
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Raun frient Passus
DLSIGNATION: J.E. Polhour