

FIELD INSPECTION REPORT

Date of Inspection : 24-12-2020	District: PURNEA
Division : DHAMAH	Length (km): 1.515 KM
Name of the Road: BARKONA DHIMA INHAT SE BARKONA PURABTOLA	
Scheme/Programme: MAINTENANCE	
Package No.: M.M. U.S.Y	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

S. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/V
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes X
f)	Contraction Joints provided or not (CC Pavement)	Yes X
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/V
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/V
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes X
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

PRAMOD
24-12-2020
(Signature)

NAME: PRAMOD KUMAR
JUNIOR ENG.