

FIELD INSPECTION REPORT

Date of Inspection :		05/12/2020	District : BHARALPUR	
Division :		RWD WORKS DIV. NARGAICHIA	Length (km) : 2.630 Km	
Name of the Road :		NH31 Marwa to Jamalpur		
Scheme/Programme :		Maintenance New Maintenance Policy 2018		
Package No. :			Road Id No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance	Ongoing	
Work is a case of :		New Connectivity/Up gradation/Maintenance	Maintenance	
Sl. No.	Parameters to be checked			Remarks
1	Pavement			Work Not Started
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Road Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
	N/A			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
	N/A			
g)	Compaction of flank/slope & raincuts if any			Yes/No
	Work Not Started			
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culvert including its painting.			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3	Cross Drainage			
a)	Whether sign boards/informatory/cautionary Boards/ km & 200m stones/Pavements roads marking are provided and maintained.			Yes/No
	Informatory Board fixed at site.			
4	Compliance History			
a)	Status of ATR's & any others			NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Vikash Kumar
(Signature)
Work Section Bihpur

NAME: VIKASH KUMAR
DESIGNATION: JUNIOR ENGINEER