

FIELD INSPECTION REPORT

Date of Inspection:	25/12/2020	Location:	Arundha
Division:	Arundha	Length (km):	3.45 km
Name of the Road:	Arundha - Pannam - Gauram Road to Sankaragudi		
Scheme/Programme:	MAINTENANCE	Year:	2020
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road surface condition	✓SU	
b)	Condition of Surfacing	✓SU	
c)	Riding Quality	✓SU	
d)	Road Camber	✓SU	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	NA/Yes/No	
f)	Contraction joints provided or not (CC Pavement)	NA/Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No/Remarks	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA/SRI	
c)	Condition of railings/slab/approach for Bridges	NA/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 27/12/2020
 (Signature)

NAME: S. Kant Prasad

DESIGNATION: E.E.