

FIELD INSPECTION REPORT

Date of Inspection: 27/12/2020		District: Nawada
Division: Nawada		Length (km): 3.66 km
Name of the Road: Barigaon to Katar Bangari road		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SRI
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA/Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA/Yes/No
g)	Compaction of flanks/slope & rainouts if any	✓Yes/No reinforced
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA/S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA/S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 (Signature) 27/12/2020

NAME: Sri Kant Prasad.

DESIGNATION: E.E.