

FIELD INSPECTION REPORT

Date of Inspection : 27/12/20	District: East Champaran
Division : Pakawati Dabhal	Length (km): 4.20
Name of the Road: Mochhuban 100 G. w. D. h. g.	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 31708602036
Status of the Project: ☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance	
Work is a case of: New Connectivity/ ☒ Up gradation/ ☐ Maintenance	New M/R

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	☒ S/U
b)	Condition of Surfacing	☒ S/U
c)	Riding Quality	☒ S/U
d)	Road Camber	☒ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	☒ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	2
Satisfactory but requires Improvement (SRI)	1
Unsatisfactory (U)	1

(Signature) *deven* 27/12/20

NAME:

Bindu Rajal

DESIGNATION:

Executive Engineer
R.W.D.

Regional Laboratory Darbhanga