

FIELD INSPECTION REPORT

Date of Inspection : 27/12/20	District: East Champaran
Division : Pakan Dajal	Length (km): 2.95
Name of the Road: Chauhaniga Paswan Tola To Talwa Gorahigh	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 31708701005
Status of the Project: ☒ Ongoing/Completed ☐ Under Maintenance	
Work is a case of: ☒ New Connectivity/Up gradation/ Maintenance ☐ New M/L	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	☒ S/U
b)	Condition of Surfacing	☒ S/U
c)	Riding Quality	☒ S/U
d)	Road Camber	☒ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	☒ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	☒ Yes/No NA
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SR!)	—
Unsatisfactory (U)	—

(Signature) *Deive*
27/12/20

NAME:

Bindu Rajak

DESIGNATION:

Executive Engineer
Regional Laboratory Darsbhangra