

FIELD INSPECTION REPORT

Date of Inspection :	26.12.2020	District :	Lakhsarai
Division :	Lakhsarai	Length (Km) :	6.9 km
Name of the Road :	Repair of road from Rangesh-Sikandra to Koli		
Scheme/Programme :	MAINTENANCE MR (3054) old		
Package No. :		Road Id No. :	20804008066
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	SRI	
b)	Condition of Surfacing	SRI	
c)	Riding Quality	SRI	
d)	Road Camber	SRI	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	/
Satisfactory but requires Improvement (SRI)	/
Unsatisfactory (U)	U

NAME : RAJIV RANJAN KUMAR
DESIGNATION : EE

Ranjan
26/12/2020
(Signature)