

FIELD INSPECTION REPORT

Date of Inspection : 26/11/2020		District : Nawada	
Division : Rangoon		Length (km) : 2.60 km	
Name of the Road : Nawhat Thana to Gajara Chater			
Scheme/Programme : MAINTENANCE		Road Id No. : 1024	
Package No. :		Road Id No. :	
Status of the Project : Ongoing/Completed/Under Maintenance			
Work is a case of : New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ SU	
b)	Condition of Surfacing	✓ SU	
c)	Riding Quality	✓ SU	
d)	Road Camber	✓ SU	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	NA/Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	NA/Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No raincuts	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	NA/✓ SRT	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA/✓ SRT	
c)	Condition of railings/slab/approach for Bridges	NA/✓ SRT/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRT)	
Unsatisfactory (U)	

393
26/11/2020
(Signature)

NAME: Sri Kant Prasad

DESIGNATION: E.E.