

FIELD INSPECTION REPORT

Date of Inspection:	27/7/2020	District:	Purulia
Division:	Murshidabad	Length (km):	6.7 km
Name of the Road:	P. No. D. Number 10	Location:	West Bengal, India
Scheme/Programme:	MAINTENANCE	Year:	2020
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work to be carried out:	New Connectivity/U/p gradation/ Maintenance		

Sl. No.	Parameters to be checked	Results
1.	Pavement	
a)	Road Junction condition	✓ Satisfactory
b)	Condition of Surfacing	✓ Satisfactory
c)	Riding Quality	✓ Satisfactory
d)	Road Camber	✓ Satisfactory
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No/Yes/No
f)	Contraction Joints provided or not (CC Pavement)	No/Yes/No
g)	Compaction of Bank/slope & reincuts if any	✓ Yes/No <i>reincuts</i>
2.	Cross Drainage	
a)	Condition of head walls of Hump pipe culverts including its painting	✓ Satisfactory
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	No/ Satisfactory
c)	Condition of railings/slab/approach for Bridges	No/ Satisfactory
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATP's & any others	No

Overall Rating :	Satisfactory (S)	S
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

31/7/2020
 (Signature)

NAME: Sri Kant Prasad

DESIGNATION: E.E.