

FIELD INSPECTION REPORT

Date of Inspection: 26/12/2020	District: Nawada	
Division: Nawada	Length (km): 3.41 km	
Name of the Road: Tilaya Bridge to Deonari Phage Singhpur		
Scheme/Programme: MAINTENANCE		
Package No.: MA-N/19-20 Nawada	Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Payment	
a)	Road function condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	NA/Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA/Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No/repeat.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA/S/SRI/L
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA/S/SRI/L
c)	Condition of railings/slab/approach for Bridges	NA/S/SRI/L
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

39
26/12/2020
(Signature)

NAME:

DESIGNATION: