

FIELD INSPECTION REPORT

Date of Inspection : 27/12/2020		District: Nawada
Division : Nawada		Length (km): 5.300/km.
Name of the Road: Nawada to Kuni		
Scheme/Programme: MAINTENANCE NEW		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	NA/Yes/No
f)	Contraction joints provided or not (CC Pavement)	NA/Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No raincuts
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA/SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA/SRI/L
c)	Condition of railings/slab/approach for Bridges	NA/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Sri Kant Prasad

DESIGNATION: E.E.

27/12/2020
(Signature)