

FIELD INSPECTION REPORT

Date of Inspection :	26/12/2020	District:	Nawada
Division :	Nawada	Length (km):	1.30 km
Name of the Road:	NH-92 to Bihra talu		
Scheme/Programme:	MAINTENANCE NEW		
Package No./SR-N/13-20/Nawada/4	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road surface condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	NA Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No	
g)	Compaction of Bank/slope & raincuts if any	✓ Yes/No raincuts	
2.	Cross Drainage		
a)	Condition of head walls in Hump pipe culverts including its painting	NA SRI	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA SRI/U	
c)	Condition of railings/slab/approach for Bridges	NA SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

33
26/12/2020
(Signature)

NAME: Sri Kant Prasad

DESIGNATION: E.E.