

FIELD INSPECTION REPORT

Date of Inspection : 26/12/2020	District: Nanded
Division : Nanded	Length (km): 1.5 km.
Name of the Road: Nanded college to Sahaswara	
Scheme/Programme:	MAINTENANCE New
Package No: N/A-N 19-20 Nanded-10	Road Id No:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No remarks
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SRI
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 26/12/2020
 (Signature)

NAME: Sri Kant Prasad

DESIGNATION: E.E.