

FIELD INSPECTION REPORT

Date of Inspection : 26/11/2020	District: NAWADA	
Division : NAWADA	Length (km): 1-100km	
Name of the Road: BAYANA TO CHURUHA MK		
Scheme/Programme:	MAINTENANCE NEW	
Package No.: PAR-4/15-20 NAWADA	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Continuity of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	NA/NO
f)	Contraction Joints provided or not (CC Pavement)	NA/Yes/No
g)	Compaction of flank/slope & rubouts if any	✓Yes/No/Unsat.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA/SRI
c)	Condition of railings/slab/approach for Bridges	NA/SRI/✓U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

29
26/11/2020
(Signature)

NAME: Sri Kant Prasad

DESIGNATION: E.E