

FIELD INSPECTION REPORT

Date of Inspection: 26/12/2020		District: Nalanda
Division: Nawada		Length (km): 3.65 km
Name of the Road: Handiya to Pachaya Tak		
Scheme/Programme: MAINTENANCE NEW		Road Id No.:
Package No.:		Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SU
b)	Condition of Surfacing	✓ SU
c)	Riding Quality	✓ SU
d)	Road Camber	✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No remarks.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA SRI/L
c)	Condition of railings/slab/approach for Bridges	NA SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 26/12/2020
 (Signature)

NAME: Sankant Prasad.

DESIGNATION: E.E.