

FIELD INSPECTION REPORT

Date of Inspection : 27/12/2010	District: Nagpur
Division: Nagpur	Length (km): 1.00 km
Name of the Road: existing new Ridge Road to Bhinhar new	Project Name:
Scheme/Programme: MAINTENANCE New	Road Id No.:
Package No.: PDR - 1419 no. Narmada 73	Status of the Project: Ongoing/Completed/Under Maintenance
Work is a case of: New Connectivity/ Upgradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SRU
b)	Condition of Surfacing	✓ SRU
c)	Riding Quality	✓ SRU
d)	Road Chamber	✓ SRU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of RCC Pavement	NA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of bank/slope & radii curv if any	Yes/No/Not Applicable
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA/SRER
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA/SRER
c)	Condition of railings/slab/approach for Bridges	NA/SRER/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating	Satisfactory (S)	S
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

393
27/12/2010
(Signature)

NAME: *Sir Venk Prabhu*

DESIGNATION: E-E