

FIELD INSPECTION REPORT

Date of Inspection :- 23.12.20		District :- Khajuraho	
Division :- Khajuraho		Length (Km) :- 0.825	
Name of Road :- L062 - T05 Bagmuliya to Sarhahi			
Scheme/Programme :- P.H.G.S.Y		Maintenance	
Package No. :-		Road ID No. :-	
Status of Project :- 5th years Maint.		Ongoing/Complete/Under Maintenance ☒	
Work is a case of :-		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	☒ S/U
b)	Condition of Surface	☒ S/U
c)	Riding Quality	☒ S/U
d)	Road Camber	☒ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ☒
f)	Construction Joints provided or not (CC Pavement)	☒ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	☒ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	HA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	HA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	☒ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 23.12.20
 J. C. Pant
 (Signature)