FIELD INSPECTION REPORT

Date of I	nspection: 24	12/020	District: Katilar		
Name of	ide and a second		Barrisari Road To Hanghang Adisoasi	Tola.	
Scheme/	Programme: MAINTENANCE				
Package No.			Road ID No.		
Status of	the Project:	Onging/Completed/Under Maintenance			
Work is a	case of:	New Conne	New Connectivity/ Up Gradation/ Maintenance		
SI.No	Parameters to be Checked Rem			Remarks	
1	Pavement				
a)	Road Junction Condition			√S/U	
b)	Condition of Surfacing			\8/Û	
c)	Riding Quality			√S∕Û	
d)	Road Camber			\s/\U	
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			, Yes/No	
f)-	Contraction Joints provided or not (CC Pavement)			V€s/No	
g)	Compaction of flank/slpoe & raincuts if any			Yes/No	
2	Cross Drainage				
a)	Condition of headwalls inn Humepipe culverts including its painting			VS/ISRI/U	
b)	Condition of Abutment & Wings walls, Slab in RCC culverts			√8/SRI/U	
c)				√8/\$RI/U	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.			Yes/No	
	Compliance History				
a)	Status of ATR & any others				
Overall Gr	edina:	Satisfactor	v (S)	6 . S	
Jyerali Gi	adily.		y but requires Improvement(SRI)	SRE	

Satisfactory (S)	8. 3
Satisfactory but requires Improvement(SRI)	SRE
Unsatisfactory (U)	

Name:

Amrendra Nath Trakem

Degisnation

(Signature)