

## FIELD INSPECTION REPORT

Date of Inspection: 8.12.2020		District: Kishanganj	
Division: Kishanganj-1		Length(km):	
Name of the Road: Dhurnu pmsy Road to Gadiwasi Tola Tal.			
Scheme/Programme: GTSNY MMSY [ST]			
Package No.:		Road Id No.: 21205814012	
Status of the Project:		Ongoing/Completed /Under Maintenance	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	

Sl. No	Parameters to be checked	Remarks
1.	<b>Pavement</b>	✓ S/U
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints Provided or not ( CC Pavement)	✓ Yes/No
g)	Compaction of flank / shop & raincuts if any	✓ Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its Painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	✓ S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

*Pravind Ravidas*  
18-12-2020

(Signature)

NAME: Pravind Ravidas

J.E, RWD, Kochadhaman