## FIELD INSPECTION REPORT

Date of	finspection: .1	2.2020	District: Kishanganj		
Division	n: Kishanganj-1		Length(km): \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Name o	of the Road: \ \ e	anwarchali p	wo Roud to Mahananda tola	4412	
Scheme	e/Programme:	GTSNY MM	1,1104,100,100		
Package	e No.:		Road Id No .: 2120581401	6	
Status of the Project: Ong		Ongoing/Compl	ing/Completed /Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation / Maintenance			
\$1. No				Remarks	
1.				S/U	
a)	Road Junction Condition			S/U	
b)				S/U	
c)				S/U	
d)				S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates Yes/No				
	in case of CC Pavement.				
f)	Contraction Joints Provided or not (CC Pavement)				
g)	Compaction of flank / shop & raincuts if any Yes/No				
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting \(\sigma \)/S/SRI/U				
b)	Condition of Abutment & Wing walls, slab in RCC culverts  S/SRI/U				
c)	Condition of railings/Slab/approach for Bridges S/SRI/U				
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m Yes/No				
	stones/Pavement road markings are provided and maintained				
4.	Compliance His				
a)	Status of ATR's	& any others			

## Overall Rating:

Satisfactory(S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

(Signature)

NAME: Pravind Ravidas
J.E, RWD, Kochadhaman