

FIELD INSPECTION REPORT

Date of Inspection : 24.12.2020	District: ARARSA	
Division : FORBESGANJ	Length (km): 1.758	
Name of the Road: Nahar pul Babulul Paswan Tola TO ward no-13 Paswan mullon Tola		
Scheme/Programme: MAINTENANCE	Road Id No.:	
Package No.:	Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:	New/Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating S :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

24/12/2020
JE

(Signature)

NAME: