FIELD INSPECTION REPORT

Date of Inspection : \\	-12-20	District: Grobalgany		
Division: RWD WD	Grobaldani	Length (km): 4.850 KM		
Name of the Road: Su	Pauli RED mad	purana pundayat Bhawanse	Subaul	laund tola
Scheme/Programme:	MAINTENANCE	MMC/3X (MB)	Though	Malgaramipunk
Package No.:		Road Id No.:		road,
Status of the Project:	Ongoing/Completed	d/Under Maintenance	. 19	
Work is a case of:	New Connectivity/	Jp gradation/ Maintenance		

SI. No.	Parameters to be checked	Remarks
1.	Pavement	are since
(a)	Road Junction condition	S/U
b)	Condition of Surfacing	Š/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.16	Cross Drainage +	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Farolture	- 1.
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
	Compliance History	
1) [5	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	_
Satisfactory but requires Improvement (SRI)	RI
Unsatisfactory (U)	

11-12-20 (Signature)

NAME: Subhash chandra Verma

DESIGNATION: 3.E.