

FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020	District: Muzaffarpur
Division : Muzaffarpur East-1	Length (km): 2.025 KM
Name of the Road: Tola Jagannathpur to Bangra thoda	
Scheme/Programme:	MAINTENANCE PMSY
Package No.: BR 232-366	Road Id No.: 315072 02352
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Some 200m post missing Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Road Surface and flank damaged due to heavy rain and flood.

NAME: Bijendra Kumar
DESIGNATION: JE
RWDLW)
Kyrhani

K. Anil Kumar
(Signature)
22/12/20
AE
RWDLW)
Kyrhani