

FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020		District: Muzaffarpur
Division : Muzaffarpur East-1		Length (km): 1.80 Km
Name of the Road: NH-33 to Chandrabali Gujra Tila		
Scheme/Programme: MAINTENANCE MHGy (SC)		
Package No.:		Road Id No.: 31577 213018
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Some 200m post missing. Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME:

Bijendra Kumar
22.12.2020

DESIGNATION: JE/RWD/LW
Kurnahi

K. Anil K.
22/12/20
(Signature)
AE
RWD/LW
Kurnahi