FIELD INSPECTION REPORT

		0 10 0100	District: Darbhangs	
Date of Inspection			1 1 1 1 2 2 1 3	
District O hull			Length (km): 3.363	
Name of	the Road:	(0) Cahon	rpur do Rompu	- agene
	Programme:	MAINTENANCE	,	
Package	No.: BR-	10R-291	Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement	The state of the s		

Sl. No.	Parameters to be checked		
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U S/U	
c)	Riding Quality		
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		
3.	Roa Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others	1- 1	

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

POWS NAMIE: 2000 DESIGNATION:

(Signature)