MMASY-SC FIELD INSPECTION REPORT

Date of 1	Inspection:		THOU REPORT	
Division: Samartipu		26 12 2000	District: Samartifuz	
Name of	41 1		Length (km): 2.080 Km	
	Programme:	MAINTENANCE	nopus Lozz Tak	
Package	No.:	THE TOTAL CE	Road Id No.:	
Status o	f the Project:	Ongoing/Completed	/Under Maintenanee	
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to		Remarks
1.	Pavement		Meller (1905) i de la compaña de la comp	
a)	Road Junction condition			SHU
b)-	Condition of Surfacing			SHU
c)	Riding Quality			SAU
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Draina	ge		
a)	Condition of head walls in Hume pipe culverts including its painting			s/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnitu	re 🐫 💮		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR	's & any others		_No -

Overall Rating

Satisfactory (S)	3	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

(Signature)

NAME: RISHI RAJ (JE)