MMGSY-SC FIELD INSPECTION REPORT

Date of Inspection: 22/12/2020		District: Samartipuz	
Division: Samartipur		Length (km):	
Name of the Road: Pu	rnahi shankaz d	while to Amiri Rai ke mil	li.
- Tobietine.	MAINTENANCE	Court Rat Ration	
Package No.:		Road Id No.:	
Status of the Project:			
Work is a case of:	a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to	be checked	Remarks
1. Pavement		用"水"。 特别的"水"的"水"。 1883年,1883年,1883年	5000000000000000000000000000000000000
a) Road Junction	Road Junction condition		
b) Condition of	Condition of Surfacing		
c) Riding Qualit	Riding Quality		
The state of the s	Road Camber		
aggregates in	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
	Contraction Joints provided or not (CC Pavement)		
	Compaction of flank/slope & raincuts if any		
2. Cross Drain:	ige		
a) Condition of	Condition of head walls in Hume pipe culverts including its painting		
1.0.0	Condition of Abutment & Wing walls, Slab in RCC culverts		
The first the second of the se	Condition of railings/slab/approach for Bridges		
3. Road Furnit	Road Furniture		
a) Whether sign stones/Pavem	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4. Compliance	Compliance History		
a) Status of ATI	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	j. 1

(Signature)

NAME: RISHI PAJ (JE)