

FIELD INSPECTION REPORT

Date of Inspection :	15.12.20	District:	Smashtipur
Division :	Datari	Length (km):	1.680 km / 1.880 km
Name of the Road:	mehudina gr Bazar to Kursaha Nahar yak		
Scheme/Programme:	MAINTENANCE		
Package No.:	N/A	Road Id No.:	N/A
Status of the Project:	~~Ongoing/Completed~~ Under Maintenance		
Work is a case of:	~~New Connectivity/Up gradation~~ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	~~S/SRI/U~~ N/A	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	~~S/SRI/U~~ N/A	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No, any ATR	

Overall Rating :

Satisfactory (S)	Satisfactory (S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: shyamkandan Kumar

DESIGNATION: AE

Shyam
15/12/20
(Signature)