FIELD INSPECTION REPORT

Date of Inspection :	21.12.2020	**District:**	BUXAR
Division :	DUMRAON	**Length (km):**	0.700 KM
Name of the Road:	MATHILA NARAYANPUR ROAD TO MATHILA MIYA TOLI.		
Scheme/Programme:	MAINTENANCE		
Package No.:		**Road Id No.:**	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	**Pavement**	
a)	Road Junction condition	✓ S/U S
b)	Condition of Surfacing	✓ S/U S
c)	Riding Quality	✓ S/U S
d)	Road Camber	✓ S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓ NO
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No NO
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No Yes
2.	**Cross Drainage**	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	**Road Furniture**	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No NO Maintained
4.	**Compliance History**	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

21.12.2020
J-E

21.12.20

(Signature)

NAME: