

|                                                         |  |                                           |
|---------------------------------------------------------|--|-------------------------------------------|
| Date of Inspection :                                    |  | District: Buxar                           |
| Division : Dumraon                                      |  | Length (km): 0.400 km                     |
| Name of the Road: Korum Sarai hqfday path to Koiri talu |  |                                           |
| Scheme/Programme: MAINTENANCE                           |  | Gr. T. S. N.Y.                            |
| Package No.:                                            |  | Road Id No.:                              |
| Status of the Project:                                  |  | Ongoing/Completed/Under Maintenance       |
| Work is a case of:                                      |  | New Connectivity/Up gradation Maintenance |

| Sl. No. | Parameters to be checked                                                                                             | Remarks  |
|---------|----------------------------------------------------------------------------------------------------------------------|----------|
| 1.      | <b>Pavement</b>                                                                                                      |          |
| a)      | Road Junction condition                                                                                              | ✓ U      |
| b)      | Condition of Surfacing                                                                                               | ✓ SU     |
| c)      | Riding Quality                                                                                                       | ✓ U      |
| d)      | Road Camber                                                                                                          | SU       |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No   |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No   |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No   |
| 2.      | <b>Cross Drainage</b>                                                                                                |          |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U  |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U  |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U  |
| 3.      | <b>Road Furniture</b>                                                                                                |          |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓ |
| 4.      | <b>Compliance History</b>                                                                                            |          |
| a)      | Status of ATR's & any others                                                                                         | NO       |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

'S'

(Signature)

NAME:

DESIGNATION:

Uy  
22/12/20  
SE

A  
22/12/20  
SE