

FIELD INSPECTION REPORT

Date of Inspection : 24/12/2020
District: Purnea
Length (km): 0.675 Km

Division : R.W.D. Div. Purnea
Name of the Road: Bhugipachhim To Bhugipachhim To 19

Scheme/Programme: MAINTENANCE
Road Id No.:

Package No.:
Status of the Project: Ongoing/Completed/Under Maintenance

Work is a case of: New Connectivity/Up gradation/ Maintenance

Parameters to be checked

Sl. No.	Remarks
1. Pavement	Yes/No
a) Road Junction condition	S/U SRI
b) Condition of Surfacing	Yes/No
c) Riding Quality	Yes/No
d) Road Camber	Yes/No
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f) Contraction Joints provided or not (CC Pavement)	Yes/No
g) Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage	S/SRI/U
a) Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b) Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c) Condition of railings/slab/approach for Bridges	Yes/No
3. Road Furniture	Yes/No
a) Whether sign boards/informative/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History	
a) Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	SRI
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Munirul Haque
(Signature)