FIELD INSPECTION REPORT

Date o	f Inspection: 22	H12/20 District: Watcher		
Scheme/ Programme: MAIN Package No.		PMVISY BUSAGOW to root Kland		
				Road ID No.
		nging/Completed/Under Maintenance		
				New Connectivity/ Up Gradation/ Maintenance
SLNo		Parameters to be Checked	T. Transport	
1	Pavement	The state of the s	Remarks	
a)	Road Junction Co	ondition	S/U	
b)	Condition of Surfacing		S/U	
c)	Riding Quality			
d)	Road Camber		'S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No	
n	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slpoe & raincuts if any		Yes/No	
2	Cross Drainage			
a)	Condition of headwalls inn Humepipe culverts including its painting S/SRI/U N			
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		Carried States	
c)	Condition of railings/slabs//approach for Bridges		S/SRI/U M	
3.	Rond Furniture			
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.			
A	Compliance History			
a)	Status of ATR & a	iny others		
verall G	rading:	Satisfactory (S)		
		Satisfactory but requires Improvement(SPI)	-33 -	

Name Ranchaldsa Ban Degistration Junior Engineer

Unsatisfactory (U)

