

FIELD INSPECTION REPORT

Date of Inspection: 19.12.20		District: Kachhar
Name of Road:	SE28 to Ganga barath charanman primary school	
Scheme/Programme:	MAINTENANCE	
Package No.		
Status of the Project:	Road ID No.	
Work is a case of:	Ongoing/Completed/Under Maintenance	
SL No.	New Connectivity/ Up Gradation/ Maintenance	
1	Pavement	Remarks
a)	Road Junction Condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Culverts	
a)	Condition of headwalls in Humpire culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slabs/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.	Yes/No
4	Compliance Hours	
a)	Status of ATR & any others	No

Overall Grading:

Satisfactory (S)	S
Satisfactory but requires Improvement(SRI)	
Unsatisfactory (U)	

Name: S W V Harayom Mandal
 Designation: AERWD (sub) In Amdebad

(Signature) 19/12/20