

FIELD INSPECTION REPORT


M-75 NY

Date of Inspection : 19/12/20		District: Varshali
Division : Hq. J. D. 2		Length (km): 0.50
Name of the Road: Amet Singh Asthan Se Premneshwar Nam Nagar Pankaj Bhatt		
Scheme/Programme: MAINTENANCE		
Package No.:	Road Id No.:	
Status of the Project: ☒ Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

M. A

Overall Rating :

Satisfactory (S) ✓	S
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	


 19/12/20
 J-E
 (Signature)

NAME:

DESIGNATION: