FIELD INSPECTION REPORT

Date of	Inspection:	12/12/20	District: East chamfara	™
Division	n:		Length (km): 2.40 6 Kil	ч,
Name o	f the Road:	,	Turkaulia to Parshu	sampur
	/Programme:	MAINTENANCE	PMGSY	
Package No.: BR-11R-605 Road Id No.:				
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance				
Sl. No.		Parameters to	be checked	Remarks
1,	Pavement		ing and the second of the seco	in .
a)	Road Junction condition			~ \$∕U
b)	Condition of Surfacing			-8/U
c)	Riding Quality			48 /Ú
d)	Road Camber			~8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainag	(e j 1)		
a)	Condition of head walls in Hume pipe culverts including its painting			-8/SRI/U
b) ·	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of ra	ilings/slab/approach i	for Bridges	S/SRI/U
3.	Road Furnitur	•		Andrew Andrew
a)			cautionary Board/km & 200m provided and maintained	Yes/No
4.	Compliance H	istory		

Overall Rating

a)

Satisfactory (S)	(\$)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Cold #10120

-414.

(Signature)

NAME:

MoRoshwar Sharmar

Status of ATR's & any others

DESIGNATION:

2.6.