FIELD INSPECTION REPORT

Date of Inspection :	·	District: Dartha-89	
miliani Qualbus		Length (km): 600	
Name of the Road:	eni Narayan Il	a House to Harizan Fila Bikupat	
Scheme/Programme:	MAINTENANCE		
	76754 (34)	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	√S/U	
b)	Condition of Surfacing	~S/U	
c)	Riding Quality		
d)	Road Camber	√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	_Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	√Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	∽S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	⊂S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	∟S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	9
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

DESIGNATION:

(Signature)